

**From:** Karen Pickett  
**To:** [Koch, Kristine](#)  
**Cc:** [Evan Griffiths - CH2MHill \(Evan.Griffiths@CH2M.com\)](#)  
**Subject:** Re: Point Ruston  
**Date:** Thursday, March 01, 2018 1:16:17 PM

---

They were doing utility work in and around Bldg. 6 well before November, and by October they were starting the foundations. By mid-November they had the rat slabs poured in the deep central footings and were placing rebar for the rest of the footing. I have more pictures if you need them. Some of these are focused on the fencing, but you can see the excavation equipment in the background. All the photos are date stamped.

I'm headed out for a game, but will check back after about 3pm. Feel free to call if you have any questions before then.

Thanks,  
Karen

On Thu, Mar 1, 2018 at 12:43 PM, Koch, Kristine <[Koch.Kristine@epa.gov](mailto:Koch.Kristine@epa.gov)> wrote:

Karen – Do you have any photos of Building 6 taken during the month of November 2017? Did you note any days of construction (building footings)?

Kristine Koch  
Remedial Project Manager  
USEPA, Office of Environmental Cleanup

U. S. Environmental Protection Agency  
Region 10  
[1200 Sixth Avenue, Suite 900, M/S](#) ECL-122  
Seattle, Washington 98101-3140

[\(206\)553-6705](tel:(206)553-6705)  
(206)553-8581 (fax)  
[1-800-424-4372](tel:1-800-424-4372) extension 6705 (M-F, 8-4 Pacific Time, only)

--

*Karen Pickett, MBA*  
*KWP Enterprises, LLC*  
*(253) 228-8529*

(b) (6)